

SR-7 Crash Analysis

Created on May 19, 2020


Created by Aron Baker

Data extents: January 1, 2010 to December 31, 2019



Applied Filters

Route ID = 0007P MP: 0.01 - 18.299



Total Crashes	44	Fatal Crashes	2
---------------	----	---------------	---

Summary	
Total Crashes	44
Fatal Crashes	2
Alcohol Related Crashes	5
CMV Crashes	3
Fixed Object Crashes	13
Pedestrian Crashes	0
Cyclist Crashes	0
Motorcycle Crashes	3
Wild Animal Crashes	12

Severity		
No injury/PDO	32	72.73%
Suspected Serious Injury	5	11.36%
Possible Injury	3	6.82%
Fatal	2	4.55%
Suspected Minor Injury	2	4.55%

Manner of Collision		
Single Vehicle	38	86.36%
Angle	3	6.82%
Head On (front-to-front)	1	2.27%
Sideswipe Opposite Direction	1	2.27%
Sideswipe Same Direction	1	2.27%
Front to Rear	0	0.00%
Not Provided		
Other		
Parked Vehicle		
Rear to Rear		
Rear to Side		
Unknown		

Crash Date Time (Year)		
2010	1	2.27%
2011	1	2.27%
2012	1	2.27%
2013	1	2.27%
2014	5	11.36%
2015	4	9.09%
2016	5	11.36%
2017	10	22.73%
2018	8	18.18%
2019	8	18.18%

Most Harmful Events		
Animal - Wild	12	27.27%
Overturn/Rollover	11	25.00%
Other Motor Vehicle in Transport	6	13.64%
Traffic Sign Support	4	9.09%
Embankment	3	6.82%
Fire/Explosion	2	4.55%
Cargo/Equipment Loss or Shift	1	2.27%
Concrete Barrier	1	2.27%
Ditch	1	2.27%
Fence	1	2.27%
Guardrail End Section	1	2.27%
Other Fixed Object	1	2.27%
Access Control Cable	0	0.00%

Animal - Domestic
 Bridge Overhead Structure
 Bridge Pier or Support
 Bridge Rail
 Building
 Cable Barrier
 Cable Barrier End Section
 Concrete Sloped End Section
 Crash Cushion
 Culvert
 Curb
 Delineator Post
 Fell/Jumped From Motor Vehicle
 Fire Hydrant
 Freight Rail
 Guardrail
 Immersion
 Invalid
 Jackknife
 Light Rail
 Mailbox
 Mailbox/Fire Hydrant
 No Damage or Injury, This Vehicle
 Not Applicable
 Not Provided
 Other Non-Collision*
 Other Non-Fixed Object*
 Other Post, Pole or Support
 Other Traffic Barrier
 Parked Motor Vehicle (off roadway)
 Passenger Heavy Rail
 Pedalcycle
 Pedestrian
 Skates, Scooters, Skateboards
 Snow Bank
 Thrown or Fallen Object
 Traffic Signal Support
 Tree/Shrubbery
 Utility Box
 Utility Pole/Light Support
 Vehicle Cargo, Part, or Object in Motion
 Work Zone/Maintenance Equipment

Roadway Surface Condition

Dry	36	81.82%
Sand, Dirt, Gravel	3	6.82%
Wet	3	6.82%
Slush	1	2.27%
Snow	1	2.27%
10	0	0.00%
11		
12		
Dirt		
Gravel		
Ice		
Mud		
Not Provided		
Oil		
Other		

Sand
Unknown
Water (standing,moving)

Weather Condition		
Clear	35	79.55%
Cloudy	5	11.36%
Rain	2	4.55%
Snowing	2	4.55%
Blowing Sand, Soil, Dirt Blowing Snow Fog, Smog Not Provided Severe Crosswinds Sleet, Hail Unknown	0	0.00%

Light Condition		
Daylight	22	50.00%
Dark - Not Lighted	15	34.09%
Dawn	4	9.09%
Dark - Lighted	2	4.55%
Dusk	1	2.27%
Dark - Unknown Lighting Not Provided Unknown	0	0.00%

Powered by

